

# Incident Learning: Medical Treatment Case

**DATE OF INCIDENT** : December 6, 2019

## BRIEF DESCRIPTION OF INCIDENT

A Rotating fitter (IP) was assembling a pump bearing housing and was applying gasket compound to the cover. While pressing the gasket compound tube, the compound squirted under the IP's safety glasses and into the right eye, resulting in an irritation to the right eye.



# What are the learnings for implementation?

- **KEY FINDINGS**

- The eye protection was not fitted correctly to adequately protect the IP's eyes.

- **LESSONS LEARNT**

- Always follow the manufactures recommended PPE as stipulated in the Safety Data Sheet [SDS].
- Ensure PPE fits correctly and is adequate for the task being performed;