

Incident Learning: Near Miss

BRIEF DESCRIPTION OF INCIDENT (08 September 2021)

A process technician [PT] was in the process of conducting structured rounds when the PT noticed a redundant line (section of pipe) had failed within the overhead pipe rack running across utilities to the crude unit.

Consequence: No consequence however, There is a risk of the piping falling from the pipe rack to grade.

RECOMMENDATIONS

Pending the completion of the investigation, the following is recommended:

- Barricade the roadway and area to prevent access into the area by pedestrians and vehicles.
- Scope and remove failed line for removal to make safe of the area.
- Inspect redundant piping to establish integrity status.