

# Incident Learning: What happened?

- Share basic information regarding the incident
  - A front-end loader was building a small ramp for a new crane pad. The operator was traveling back and forth between a pile of gravel and the crane pad. The spotter was bumped while the loader was backing up to get another load.
- Actual and potential consequences
  - Actual level 1
  - Potential Level 3
- Add picture if applicable



# What are the learnings for implementation?

- We are concerned with the key learnings for discussion
  - Spotters/Operators should discuss the intended operation of mobile equipment prior to commencing the work
  - Spotters should understand the Operators “blind-spots” and stay visible to the operator while the equipment is in motion
  - Spotters should position themselves to see and avoid the hazards of equipment in motion and the hazards of the work environment
  - Operators should stop if they lose sight of the spotter.

# HSSE MOMENT SHARING ROSTER

<b>REFINERY</b>	<b>RMSF MEETING</b>
<b>NATREF</b>	<b>Q2 2017</b>
<b>PETROSA</b>	<b>Q3 2017</b>
<b>ENREF</b>	<b>Q4 2017</b>
<b>CHEVREF</b>	<b>Q1 2018</b>
<b>SASOL</b>	<b>Q2 2018</b>
<b>SAPREF</b>	<b>Q3 2018</b>