

Truck Fire Incidents, latest 23rd June 2022.

Engen truck fires – There have been 3 fires related to tyres of the trucks, all these resulted in the fire spreading from the tyre to the truck. The latest fire happening in our depot.

ROOT CAUSES

- Binding Brakes
- Partially inflated tyres
- Poor Road Conditions

KEY LEARNINGS

Smoke from any tryes (Any Smoke)
Drag of truck – Truck feels like it has no power

Air Loss – Warning lights

- Previous records of air loss captured on PDC and not repaired
- Sudden Air Loss

Under inflated tyres

- PDC checks
- Potholes – Sudden loss
- Alignment feels out

People trying to warn\flag down the BTO.
 Be careful with this due to the high Hi-jacking rate in SA.

