

# Incident Learning: What happened?

- At Approximately 15H30pm a contractor employee was in the process of offloading empty gas cylinders from a stationary truck parked approximately four (4) meters from the entrance of the consumable store.
- Strong winds blew one of the 14 Kg cylinders on the truck over and during this action the employee was struck and sustained a cut on his upper right eyebrow by a falling cylinder gas bottle at a consumable store close to the Unitrans Building.



This is the Cylinder that hit the employee in the Right Eyebrow

# What are the learnings for implementation?

---

- Always use your LPSA
- Be vigilant on your surroundings