

Incident Learning: What happened?

- On Sunday 11th August at approximately 1:20PM, a worker sustained an injury to the right knee and left shin while on-board a vessel at the Cape Town Harbors. He was executing a routine connection and disconnection of the loading arms to the manifold to backload the docked vessel. While standing on the drip tray, moving to ascend the ladder, he tripped and fell forward, knocking his knee and shin.



What are the learnings for implementation?

- Always apply LPISA when conducting Task
- Always stop and re-assess when conditions have changed.
- Always be vigilant of your surroundings.