

Incident Learning: What happened?



On 15 November 2018 at approximately 10h43 whilst the Service Provider employee was lifting the steel sheet cover of the hydrocarbon drain for water to drain, his right middle finger was cut by a piece of glass.

What are the learnings for implementation?

- All the tasks that are performed in the lab must be assessed and hazards identified must be incorporated in the procedures.
- PVC gloves are slippery when used while washing glassware resulting in frequent breaking of glassware.