



PetroSA

The Petroleum Oil and Gas Corporation
of South Africa (SOC) Ltd

Injury On Duty Flash

- B-Parking Stairs: **GTL Refinery** -

...think Safety..., work Safely!

Safety Moment – 12 May 2022

Safety Team





PetroSA

IOD MTC – 11 May 2022: GTL Refinery

- #9422: Staircase ex B-Parking Area next to Admin @ 07H55 -



What Happened..?

Whilst descending steps injured missed a step, and fell on both knees rolling over. Presented with bruised knees and swollen left ankle. Taken to Bayview for Scans/Xrays. Colleague in Pain.


Possible Cause(s)..?

- Concrete step cracked.
- Safety Warning Signage.
- Safety Rule – Pictogram – 3point Contact.
- Distraction.
- Mind/Focus on Hazard.

Lesson...to Me(You)(Us)!

- *Recognise that a staircase is a hazard, give it the focus and attention you deserve: **3-Point Contact, Watch where you step.***
- *Let Us Not Injure Ourselves!*





**NO SAFETY
KNOW
PAIN**



**for Always Having
Your **Eye** on the **Hazard!****