

Incident Learning: What happened?

Medical Treatment Case: Laceration requiring stitches

- On 13th March 2020 at approximately 15H20, a contractor employee was cutting a 4-inch pipe in an awkward position using a grinder in a congested piping area. The grinder bounced on the metal pipe and hit the employee on the back of the hand cutting through the leather glove



Grinder guard positioning



Grinder's disk cut through glove

Key Communication Points



- When using power tools consider if the work space is suitable to use.
- Always wear the appropriate (task specific PPE) when performing work activities.